

FRA Purpose Built Blocks

Responsible Person:	Islington Council
Auditor:	{REDACTED}
Location:	Greenaway House, Fernsbury Street, London WC1X 0HZ
Area Housing Office:	PURPOSE-BUILT BLOCKS - ST JOHN STREET
Date of Audit	03/07/2020
Suggested Review	



Overall Assessment of Fire Risk

Hazard from Fire:	Normal
Consequences Life:	Slight Harm
Overall Risk from Fire:	Tolerable

PRIVATE

THIS DOCUMENT IS UNCONTROLLED WHEN PRINTED

Introduction

This report has been completed in compliance with Article 9 of the Regulatory Reform (Fire Safety) Order 2005.

The purpose of this report is to provide an assessment of the risk to life from fire, and where appropriate, to make recommendations to ensure compliance with fire safety legislation.

The assessment was completed on the situation observed while at the premises and on information provided, either verbally or in writing.

The assessment does not involve destructive exposure, and it is not always possible to see in all rooms and areas, not inspect less readily accessible areas such as above ceilings. It is therefore necessary to rely on a degree of sampling and also reasonable assumptions and judgments.

The report represents only the best judgment of the auditor involved in the preparation and is based, in part, on information provided by others, such as other staff members or contractors.

Note that, although the purpose is to place the fire risk in context, the approach to fire safety risk assessment is subjective and for guidance only.

All hazards and deficiencies identified in this fire safety risk assessment should be addressed by implementing all the recommendations contained in the action summary.

General Building Information

Premises Description and/or Other Relevant Information:

Two enclosed staircases leading to open balcony approaches on 2nd & 4th floors only, one staircase also has a lift. No common access to 1st, 3rd or 5th floors (believed to be the upper levels of maisonettes). Direct access to flats 1-6 on ground floor via individual front gardens. Block built around 1935.

Brief Details of the Block Construction:

Concrete floors & stairs; brick walls; May have some timber floors separating upper/lower levels within maisonettes.

Number of Floors:	6	Total Number of Units:	28
Number of Emergency Exits:	4 (front & rear exit from both stairways)	Number of Employees Present:	0+
Approximate Number of Residents:	70	Maximum Number of members of the Public at any one time:	25
Disabled Occupants:	Not Known		

Fire Loss Experience (if known):

Not known

Audit Details

Section	2. Identifying the Fire Hazards	
Sub-Section	2.1 Sources of Ignition	
Question	2.1.1 Naked flames	No
Question	2.1.2 Electrical sources	Low Risk
Question	2.1.3 Acts of nature eg lightning	Low Risk

Sub-Section	2.2 Sources of Fuel	
Question	2.2.1 Combustive materials	Low Risk

Sub-Section	2.3 Sources of Oxygen	
Question	2.3.1 Sources of oxygen other than naturally occurring?	None

Section	3. Identifying People at Risk	
Question	3.1 Are employees and/or visitors at risk from fire hazards?	Low Risk
Question	3.2 Are residents at risk from fire hazards?	Low Risk
Question	3.3 Are vulnerable persons at risk from the fire hazards?	Low Risk

Section	4. Evaluating the Fire Hazards	
Question	4.1 Do the premises have an effective smoking policy?	Medium Risk
<i>"No Smoking" signage is displayed in the premises.</i>		
ACTION	Remind residents of the smoking policy, monitor adherence & take enforcement action as necessary.	

Findings (ISSUE)	{REDACTED}	Action & Completion By 05/01/2021
Question	4.2 Does electrical equipment or wiring appear to be free from damage or misuse?	Low Risk
<i>Electrical intake cupboards are routinely checked as part of the Quality Assurance Officer (QAO) inspection regime, which is documented. Estate/Caretaking Services will ensure doors remain adequately secured when not in use.</i>		
Question	4.3 Have satisfactory measures been taken to reduce the risk of arson?	Low Risk
<i>Block entry security system. Refuse & recycling stored away from block.</i>		
Question	4.4 Do the premises have any protection against acts such as lightning	Low Risk
<i>The installation of lightning protection is to be considered as part of future Cyclical Improvement Programme (CIP) works, following assessment by specialists.</i>		
Question	4.5 Are the common and landlord areas of the premises free from an accumulation of combustible materials, storage and/or waste?	Medium Risk
<i>Islington Council operates a managed use policy, where items of limited combustibility such as door mats, plant pots etc. are generally permitted. Regular inspections are carried out by Quality Assurance Officers (QAO's) to ensure this policy is being adhered to and that properties are kept free of an accumulation of combustible waste. A 'zero tolerance' policy will be introduced where residents are unable to adhere to a sensible managed use arrangement.</i>		
ACTION	Clear waste/storage/combustibles from common/Landlord areas and advise residents of the policy for waste disposal and take enforcement action where appropriate.	
Findings (ISSUE)	{REDACTED}	Action & Completion By 05/01/2021
ACTION	Clear waste/storage/combustibles from common/Landlord areas and advise residents of the policy for waste disposal and take enforcement action where appropriate.	
Findings (ISSUE)	{REDACTED}	Action & Completion By 05/01/2021
Question	4.6 Are wall, ceiling or floor coverings of a fire-resistant nature?	Low Risk

Question	4.7 Are holes in fire resistant partitions (service ducts, fire compartments or flues) within the premises adequately fire stopped?	Low Risk
ACTION	Service risers should be inspected and adequate fire stopping and separation provided between differing services.	
Findings (ISSUE)	The boarding within the electrical intake cupboard, on the ground floor in entrance to 7-28, which appears to separate the water main from the electrical installation has not been fixed back in place.	Action & Completion By 05/07/2021
Question	4.8 Is fire separation on the means of escape routes adequately maintained?	Low Risk
Question	4.9 Are there arrangements to ensure the safe evacuation of the premises where it is used for sleeping?	Low Risk
<p><i>Security gates fitted within block to individual dwellings.</i></p> <p><i>Islington Council recognises the balance between safety and security, adopting an advisory approach to security gates/grills and warning residents of the dangers/potential delays to the fire and rescue authority. Where gates/grills hinder access/egress to more than one property they will be disabled and/or removed immediately. The Construction and Fire Safety Team (CFST) will write to residents with gates installed periodically to refresh this information. This will also be repeated through resident newsletters and web articles etc. periodically.</i></p>		
Question	4.10 Are evacuation arrangements for vulnerable people suitable/sufficient?	Low Risk
ACTION	{REDACTED}	
Findings (ISSUE)	{REDACTED}	Action & Completion By 05/01/2021
Question	4.11 Are the escape routes identified with effective signage to allow for all people to safely evacuate the premises in the event of an emergency?	Yes
<p><i>Simple stairway exit routes.</i></p>		

Section	5. Means of Escape	
Question	5.1 Are the available escape routes and exit widths suitable and sufficient for the number of people within the premises?	Yes

Question	5.2 Are the available escape routes and widths suitable and sufficient for the physical layout of the premises?	Yes
Question	5.3 Are all pathways corridors and escape routes (internal and external) free from obstruction or other fire risks?	Low Risk
<i>See 4.5.</i>		
Question	5.4 Are escape routes likely to be compromised in early stages of fire? i.e unprotected staircase or inadequate ventilation	Low Risk
<i>Open-able windows on stairway. Open balcony approach.</i>		
Question	5.5 Is the lighting adequate?	Low Risk
<i>No emergency lighting on means of escape.</i>		
<i>Islington Council will install emergency lighting in purpose built blocks of flats (2 storey+) in line with its planned upgrade and renewal/cyclical improvement programme/CIP. High rise blocks (10 storey+) and those with complex layouts will be completed as a priority, with each block being assessed during the planning stages of CIP works. Properties with a simultaneous evacuation strategy will also be considered a priority.</i>		
Question	5.6 Do all exits within the premises lead to a place of reasonable or total safety?	Yes
Question	5.7 Are dwelling front entrance doors (from random sample) of a suitably fire resisting construction for the type of property and the location?	No
<i>Islington Council has established a dedicated fire safety project team to survey all flat front entrance doors (and alternative means of escape doors where applicable) and carry out upgrade or replacement works where required, in line with recommendations made in the LGG's Fire Safety in Purpose Built Blocks of Flats guidance document. For tenanted properties, as a minimum upgrade works will include the installation of a self-closing device. Surveys of leasehold properties will also be carried out, with leaseholders able to opt-in to the upgrade programme. The survey/works programme will also include communal doors where applicable, to ensure means of escape routes are suitably protected.</i>		
ACTION	Replace any missing or defective letterbox installations.	
Findings (ISSUE)	{REDACTED}	Action & Completion By 05/01/2021

ACTION	Inspect front entrance door to ensure it provides 30 minutes' fire resistance.	
Findings (ISSUE)	{REDACTED}	Action & Completion By 05/01/2021
ACTION	Inspect front entrance door to ensure it provides 30 minutes' fire resistance.	
Findings (ISSUE)	{REDACTED}	Action & Completion By 05/01/2021
Question	5.8 Are the dwelling front entrance doors (from random sample) fitted with fully functional self-closing devices?	No
<p><i>Islington Council has established a dedicated fire safety project team to survey all flat front entrance doors (and alternative means of escape doors where applicable) and carry out upgrade or replacement works where required, in line with recommendations made in the LGG's Fire Safety in Purpose Built Blocks of Flats guidance document. For tenanted properties, as a minimum upgrade works will include the installation of a self-closing device. Surveys of leasehold properties will also be carried out, with leaseholders able to opt-in to the upgrade programme. The survey/works programme will also include communal doors where applicable, to ensure means of escape routes are suitably protected.</i></p>		
Question	5.9 Are the fire doors within the common and landlord areas suitable and sufficient, and fitted where necessary, with intumescent strips and smoke seals?	Low Risk
<p><i>Islington Council has established a dedicated fire safety project team to survey all flat front entrance doors (and alternative means of escape doors where applicable) and carry out upgrade or replacement works where required, in line with recommendations made in the LGG's Fire Safety in Purpose Built Blocks of Flats guidance document. For tenanted properties, as a minimum upgrade works will include the installation of a self-closing device. Surveys of leasehold properties will also be carried out, with leaseholders able to opt-in to the upgrade programme. The survey/works programme will also include communal doors where applicable, to ensure means of escape routes are suitably protected.</i></p>		
Question	5.10 Are self-closing devices provided appropriately on fire doors within the common and landlord areas? If so, are they in working order?	Yes
Question	5.11 Are the internal fire doors indicated with the appropriate signage	Yes
Question	5.12 Do the doors used for means of escape from the premises open in direction of travel where necessary?	Yes
Question	5.13 Are doors used for means of escape from the premises provided with suitable fastenings that can be	Yes

	easily and immediately opened without the use of a key?	
<i>Entry doors are incorporated into routine Quality Assurance Officer (QAO) inspections, with any repair issues raised with Estate Maintenance Team/Housing Repairs Service.</i>		
Question	5.14 Are the floor surfaces on the escape route (internal and external) free from trip/slip hazards?	Low Risk
Question	5.15 Are Fire Service facilities and access to the premises suitable and sufficient?	Low Risk
ACTION	Consider adding fire brigade door entry overrides to doors providing access from rear of property.	
Findings (ISSUE)	Vehicular access is provided to the rear of the property. FB overrides on the rears doors could be beneficial to the Fire Service.	Action & Completion By 05/07/2021
Question	5.16 Are floor level indicators present and legible?	Yes
Question	5.17 Do Fire Services facilities such as dry/wet risers, door entry/lift overrides appear to be free from damage and vandalism?	Yes
Question	5.18 Are Fire Service facilities and controls for the premises subjected to a suitable system of maintenance and/or repair?	Yes
<i>Testing of LFB access switches is incorporated into routine Quality Assurance Officer (QAO) inspections, with any repair issues raised with Estate Maintenance Team/Housing Repairs Service.</i>		

Section	6. Detection and Warning	
Question	6.1 Do the dwellings (from random sample) appear to have suitable hard wired smoke/heat detection installed?	Low Risk
<i>Mains powered smoke/heat detection (to LD2 standard) was installed extensively to tenanted properties as part of the Decent Homes programme between 2004 & 2010. Since the conclusion of the Decent Homes programme, mains powered smoke/heat detection (LD2) is now installed as part of void property process and the cyclical (5 yearly), domestic electrical inspection/testing regime where it is not already provided. It is likely the majority of leasehold properties will not benefit from mains powered detection systems, although some grade F systems (battery operated) are likely to exist.</i>		
ACTION	Determine if the existing provision of detection installed is suitable for	

	the current layout and upgrade if required.	
Findings (ISSUE)	This block appears to contain maisonettes. Inspect internally to determine if original fire safety measures are still in place/available and adequate means of escape/warning are provided for the layout of the dwelling.	Action & Completion By 05/07/2027
Question	6.2 Are methods of detection and warning within the premises considered suitable and sufficient?	Yes

Section	7. Emergency Plans	
Question	7.1 Based upon the overall risk of fire, evaluation of fire hazards and means of escape, is the policy of "Stay put, unless affected by smoke or fire" considered adequate for the dwellings within these premises?	Yes
Question	7.2 Based upon the overall risk of fire, evaluation of fire hazards and means of escape, is the policy of "Full Evacuation" considered adequate for the dwellings within these premises?	N/A
Question	7.3 Have emergency plans been communicated to residents and other relevant people	Yes
<p><i>Fire action notice displayed in entrance lobby to block.</i></p> <p><i>The majority of purpose built blocks of flats operate on the principle that residents should 'stay put, unless directly affected by smoke, heat or fire'. This is communicated to residents through the tenant sign-up pack, regular newsletter articles and the Islington Council website, which also links to the LFB's 'know the plan' website. Caretakers are informed through periodic training.</i></p>		

Section	8. Further Surveys and Investigation	
Question	8.1 Are there any serious or suspected structural deficiencies which could lead to spread of fire beyond the dwelling of origin, warranting further investigation such as a Type 2, 3 or 4 survey?	No
Question	8.2 Are there any un-accessed areas or known voids that warrant further investigation to confirm adequate fire safety measures are in place?	Low Risk

ACTION	The roof space should be inspected to ensure that the fire separation is maintained. If the separating walls are compartment walls (a continuation of the party walls between each flat) any hatches and/or doors should provide a minimum of 60 minutes fire resistance (i.e. FD60). If the separating walls are not compartment walls but are provided to reduce the size of roof space void the provision of FD30 hatches and/or doors will be acceptable.	
Findings (ISSUE)	None	Action & Completion By 05/07/2027
Question	8.3 Are the external escape staircases and gangways for the premises subjected to a suitable system of periodic inspection, maintenance and repair?	Low Risk
<i>Routine Quality Assurance Officer (QAO) inspections include all external staircases, gangways and other such areas associated with a particular block. Defects are raised via Estate Maintenance Team/Housing Repairs Service and monitored to completion through the inspection process.</i>		
Question	8.4 Are there other types of occupancy forming part of/or within the block (shops, offices, nurseries etc)?	No
Question	8.5 Are there any other issues which may have an impact on the fire safety of the premises?	No
Question	8.6 Are the external surfaces of the building likely to promote fire spread?	No

Section	9. Overall Assessment of Fire Risk	
Question	9.1 Evaluation of overall fire hazard	Normal
Question	9.2 Evaluation of overall consequences for life safety	Slight Harm
Question	9.3 Overall evaluation of fire risk	Tolerable
Question	9.4 The most appropriate fire strategy for this building is	Stay-put
Question	9.5 Height of Building	N/A
Question	9.6 Next FRA Due	N/A

Audit Details

Section	4. Evaluating the Fire Hazards
Action Ref	0036372
Question	4.10 Are evacuation arrangements for vulnerable people suitable/sufficient?
Action Required	{REDACTED}
Action Notes	{REDACTED}
Due Date	05/01/2021
Responsible	Area Housing Office - Tenancy Management
Status	OPEN
Action Ref	0036378
Question	4.5 Are the common and landlord areas of the premises free from an accumulation of combustible materials, storage and/or waste?
Action Required	Clear waste/storage/combustibles from common/Landlord areas and advise residents of the policy for waste disposal and take enforcement action where appropriate.
Action Notes	{REDACTED}
Due Date	05/01/2021
Responsible	Area Housing Office - Tenancy Management
Status	COMPLETE
Action Ref	0036373
Question	4.7 Are holes in fire resistant partitions (service ducts, fire compartments or flues) within the premises adequately fire stopped?
Action Required	Service risers should be inspected and adequate fire stopping and separation provided between differing services.
Action Notes	The boarding within the electrical intake cupboard, on the ground floor in

	entrance to 7-28, which appears to separate the water main from the electrical installation has not been fixed back in place.
Due Date	05/07/2021
Responsible	Estate Maintenance Team
Status	COMPLETE
Action Ref	0036379
Question	4.5 Are the common and landlord areas of the premises free from an accumulation of combustible materials, storage and/or waste?
Action Required	Clear waste/storage/combustibles from common/Landlord areas and advise residents of the policy for waste disposal and take enforcement action where appropriate.
Action Notes	{REDACTED}
Due Date	05/01/2021
Responsible	Area Housing Office - Estate Services
Status	COMPLETE
Action Ref	0036381
Question	4.1 Do the premises have an effective smoking policy?
Action Required	Remind residents of the smoking policy, monitor adherence & take enforcement action as necessary.
Action Notes	{REDACTED}
Due Date	05/01/2021
Responsible	Area Housing Office - Tenancy Management
Status	COMPLETE
Section	5. Means of Escape
Action Ref	0036376

Question	5.7 Are dwelling front entrance doors (from random sample) of a suitably fire resisting construction for the type of property and the location?
Action Required	Replace any missing or defective letterbox installations.
Action Notes	{REDACTED}
Due Date	05/01/2021
Responsible	Area Housing Office - Tenancy Management
Status	COMPLETE
Action Ref	0036371
Question	5.15 Are Fire Service facilities and access to the premises suitable and sufficient?
Action Required	Consider adding fire brigade door entry overrides to doors providing access from rear of property.
Action Notes	Vehicular access is provided to the rear of the property. FB overrides on the rears doors could be beneficial to the Fire Service.
Due Date	05/07/2021
Responsible	CIP / Fire Safety Works Team
Status	OPEN
Action Ref	0036374
Question	5.7 Are dwelling front entrance doors (from random sample) of a suitably fire resisting construction for the type of property and the location?
Action Required	Inspect front entrance door to ensure it provides 30 minutes' fire resistance.
Action Notes	{REDACTED}
Due Date	05/01/2021
Responsible	CIP / Fire Safety Works Team
Status	OPEN

Action Ref	0036375
Question	5.7 Are dwelling front entrance doors (from random sample) of a suitably fire resisting construction for the type of property and the location?
Action Required	Inspect front entrance door to ensure it provides 30 minutes' fire resistance.
Action Notes	{REDACTED}
Due Date	05/01/2021
Responsible	CIP / Fire Safety Works Team
Status	OPEN
Section	6. Detection and Warning
Action Ref	0036377
Question	6.1 Do the dwellings (from random sample) appear to have suitable hard wired smoke/heat detection installed?
Action Required	Determine if the existing provision of detection installed is suitable for the current layout and upgrade if required.
Action Notes	This block appears to contain maisonettes. Inspect internally to determine if original fire safety measures are still in place/available and adequate means of escape/warning are provided for the layout of the dwelling.
Due Date	05/07/2027
Responsible	CIP / Fire Safety Works Team
Status	OPEN
Section	8. Further Surveys and Investigation
Action Ref	0036380
Question	8.2 Are there any un-accessed areas or known voids that warrant further investigation to confirm adequate fire safety measures are in place?
Action Required	The roof space should be inspected to ensure that the fire separation is

	maintained. If the separating walls are compartment walls (a continuation of the party walls between each flat) any hatches and/or doors should provide a minimum of 60 minutes fire resistance (i.e. FD60). If the separating walls are not compartment walls but are provided to reduce the size of roof space void the provision of FD30 hatches and/or doors will be acceptable.
Due Date	05/07/2027
Responsible	CIP / Fire Safety Works Team
Status	OPEN

Previous O/S Actions (as of report generation date)

None