

FRA Purpose Built Blocks

Responsible Person:	Islington Council
Auditor:	{REDACTED}
Location:	Ilford House, Dove Road, London N1 3LZ
Area Housing Office:	PURPOSE-BUILT BLOCKS - UPPER STREET EAST
Date of Audit	20/11/2020
Suggested Review	



Overall Assessment of Fire Risk

Hazard from Fire:	Normal
Consequences Life:	Moderate Harm
Overall Risk from Fire:	Moderate

PRIVATE

THIS DOCUMENT IS UNCONTROLLED WHEN PRINTED

Introduction

This report has been completed in compliance with Article 9 of the Regulatory Reform (Fire Safety) Order 2005.

The purpose of this report is to provide an assessment of the risk to life from fire, and where appropriate, to make recommendations to ensure compliance with fire safety legislation.

The assessment was completed on the situation observed while at the premises and on information provided, either verbally or in writing.

The assessment does not involve destructive exposure, and it is not always possible to see in all rooms and areas, not inspect less readily accessible areas such as above ceilings. It is therefore necessary to rely on a degree of sampling and also reasonable assumptions and judgments.

The report represents only the best judgment of the auditor involved in the preparation and is based, in part, on information provided by others, such as other staff members or contractors.

Note that, although the purpose is to place the fire risk in context, the approach to fire safety risk assessment is subjective and for guidance only.

All hazards and deficiencies identified in this fire safety risk assessment should be addressed by implementing all the recommendations contained in the action summary.

General Building Information

Premises Description and/or Other Relevant Information:

Storage rooms on each accommodation corridor. Some service risers not accessible. No access to roof from north stair. Permanent ventilation provided on each floor adjacent to the bin chute & in lift lobby area.

Brief Details of the Block Construction:

Reinforced concrete frame and floors with brick infill walls. Alternate means of escape from all floors and at ground level. FB override facility. Dry riser in north Stair. 2 Lifts with FB control.

Number of Floors:	11	Total Number of Units:	80
Number of Emergency Exits:	3 from 2 stairways	Number of Employees Present:	0+
Approximate Number of Residents:	200	Maximum Number of members of the Public at any one time:	60
Disabled Occupants:	Not Known		

Fire Loss Experience (if known):

None known

Audit Details

Section	2. Identifying the Fire Hazards	
Sub-Section	2.1 Sources of Ignition	
Question	2.1.1 Naked flames	No
Question	2.1.2 Electrical sources	Low Risk
Question	2.1.3 Acts of nature eg lightning	Low Risk

Sub-Section	2.2 Sources of Fuel	
Question	2.2.1 Combustive materials	Low Risk

Sub-Section	2.3 Sources of Oxygen	
Question	2.3.1 Sources of oxygen other than naturally occurring?	None

Section	3. Identifying People at Risk	
Question	3.1 Are employees and/or visitors at risk from fire hazards?	Low Risk
Question	3.2 Are residents at risk from fire hazards?	Low Risk
Question	3.3 Are vulnerable persons at risk from the fire hazards?	Low Risk

Section	4. Evaluating the Fire Hazards	
Question	4.1 Do the premises have an effective smoking policy?	Low Risk
	"No Smoking "signage is displayed in the premises.	
Question	4.2 Does electrical equipment or wiring appear to be free from damage or misuse?	Low Risk

Electrical intake cupboards are routinely checked as part of the Estate Service Co-ordinators' inspection regime, which is documented. Estate/Caretaking Services will ensure doors remain adequately secured when not in use.

Electrical works are currently ongoing at the block and some trunking within the common areas has been temporarily removed to facilitate this.

Repair operation of defective door release buttons.	
{REDACTED}	Action & Completion By 02/12/2021
4.3 Have satisfactory measures been taken to reduce the risk of arson?	Low Risk
Block entry security system. CCTV on estate.	
Secure doors, cupboards, risers etc to prevent unauthorised access.	
{REDACTED}	Action & Completion By 02/12/2021
4.4 Do the premises have any protection against acts such as lightning	Yes
Lightening protection evident on building.	
4.5 Are the common and landlord areas of the premises free from an accumulation of combustible materials, storage and/or waste?	Medium Risk
	{REDACTED} 4.3 Have satisfactory measures been taken to reduce the risk of arson? Block entry security system. CCTV on estate. Secure doors, cupboards, risers etc to prevent unauthorised access. {REDACTED} 4.4 Do the premises have any protection against acts such as lightning Lightening protection evident on building. 4.5 Are the common and landlord areas of the premises free from an accumulation of combustible materials,

Islington Council operates a risk based approach to managing communal areas dependent on the design layout. Where corridors are enclosed or substantially enclosed a zero tolerance approach will be adopted. Where blocks have an open corridor design a managed use policy will be in place, where items of limited combustibility such as door mats, plant pots etc. are generally permitted in line with the guidance note for fire prevention in communal areas. Regular inspections are carried out by Estate Service Co-ordinators or TMO staff to ensure this policy is being adhered to and that properties are kept free of an accumulation of combustible waste. A 'zero tolerance' policy will be introduced where residents are unable to adhere to a sensible managed use arrangement.

ACTION	Clear waste/storage/combustibles from common/Landlord areas and advise residents of the policy for waste disposal and take enforcement action where appropriate.	
Findings (ISSUE)	{REDACTED}	Action & Completion By 01/06/2021

ACTION	Clear waste/storage/combustibles from common/Landlord areas and advise residents of the policy for waste disposal and take enforcement	
Findings (ISSUE)	action where appropriate. {REDACTED}	Action & Completion By 01/06/2021
Question	4.6 Are wall, ceiling or floor coverings of a fire-resistant nature?	Low Risk
Question	4.7 Are holes in fire resistant partitions (service ducts, fire compartments or flues) within the premises adequately fire stopped?	Low Risk
	{REDACTED}	
Question	4.8 Is fire separation on the means of escape routes adequately maintained?	Low Risk
Question	4.9 Are there arrangements to ensure the safe evacuation of the premises where it is used for sleeping?	Low Risk
	Security gates fitted within block to individual dwellings.	
approach to secu and rescue auth will be disabled will write to reside	cil recognises the balance between safety and security, add rity gates/grills and warning residents of the dangers/potent ority. Where gates/grills hinder access/egress to more than and/or removed immediately. The Construction and Fire Sa ents with gates installed periodically to refresh this informati ated through resident newsletters and web articles etc. perio	tial delays to the fire one property they afety Team (CFST) ion. This will also be
Question	4.10 Are evacuation arrangements for vulnerable people suitable/sufficient?	Low Risk
	eople formerly identified but there may be occupants with v physical/mental disability, in line with the general populatio	

signage to allow for all people to safely evacuate the premises in the event of an emergency?

Section	5. Means of Escape	
Question	5.1 Are the available escape routes and exit widths suitable and sufficient for the number of people within	Yes

	the promises?	
	the premises?	
Question	5.2 Are the available escape routes and widths suitable and sufficient for the physical layout of the premises?	Yes
Question	5.3 Are all pathways corridors and escape routes (internal and external) free from obstruction or other fire risks?	Low Risk
	See 4.5.	
Question	5.4 Are escape routes likely to be compromised in early stages of fire? i.e unprotected staircase or inadequate ventilation	Low Risk
	block no longer in use. Old bin chute areas and lift lobby ent ventilation. Windows provided on both stairways (also	
Question	5.5 Is the lighting adequate?	Low Risk
Islington Council with its planned u (10 storey+) and	Emergency lighting is currently being installed within the block. Islington Council will install emergency lighting in purpose built blocks of flats (2 storey+) in line with its planned upgrade and renewal/cyclical improvement programme/CIP. High rise blocks (10 storey+) and those with complex layouts will be completed as a priority, with each block being assessed during the planning stages of CIP works. Properties with a simultaneous evacuation strategy will also be considered a priority.	
Question	5.6 Do all exits within the premises lead to a place of reasonable or total safety?	Yes
Question	5.7 Are dwelling front entrance doors (from random sample) of a suitably fire resisting construction for the type of property and the location?	Νο
	f flat entrance doors have been replaced to comply with c ock contains a significant number of leaseholder doors wh replaced.	
place to identif findings, results of	HCLG investigations and findings, Islington council, has a y all composite fire doors/sets. As this program rolls out, of the testing and certification etc. taking into consideration sessment, the complexity of the premise design, layout, a procedures, appropriate action will be taken.	dependent on the the actions raised in
(The appropria	te remedial action will be undertaken within a suitable tim managed basis).	e frame on a risk

ACTION	Inspect front entrance door to ensure it provides 30 minutes' fire resistance.	
Findings (ISSUE)	{REDACTED}	Action & Completion By 01/06/2021
ACTION	Replace damaged front entrance door to flat.	
Findings (ISSUE)	{REDACTED}	Action & Completion By 01/06/2021
Question	5.8 Are the dwelling front entrance doors (from random sample) fitted with fully functional self-closing devices?	Νο
closers are lik	oors have recently been upgraded to current standards, t kely to be in place and working, however, this block conta easeholder doors which may not have a working self-clos	ins a number of
Question	5.9 Are the fire doors within the common and landlord areas suitable and sufficient, and fitted where necessary, with intumescent strips and smoke seals?	Medium Risk
entrance door upgrade or replace Fire Safety in Pul minimum upg leasehold prope	il has established a dedicated fire safety project team to s s (and alternative means of escape doors where applicable ement works where required, in line with recommendation rpose Built Blocks of Flats guidance document. For tenan rade works will include the installation of a self-closing de erties will also be carried out, with leaseholders able to op survey/works programme will also include communal doo to ensure means of escape routes are suitably protected	ble) and carry out as made in the LGG's ated properties, as a evice. Surveys of t-in to the upgrade rs where applicable,
ACTION	Repair/adjust door installation to ensure that the door/s fully self closes into its/their frame/s.	
Findings (ISSUE)	{REDACTED}	Action & Completion By 01/06/2021
ACTION	Remove vents and repair/replace door to provide 30 minutes fire resistance	
Findings (ISSUE)	{REDACTED}	Action & Completion By 02/12/2021
Question	5.10 Are self-closing devices provided appropriately on fire doors within the common and landlord areas? If so, are they in working order?	Low Risk

Question	5.11 Are the internal fire doors indicated with the appropriate signage	Yes
Question	5.12 Do the doors used for means of escape from the premises open in direction of travel where necessary?	Yes
Question	5.13 Are doors used for means of escape from the premises provided with suitable fastenings that can be easily and immediately opened without the use of a key?	Yes
	incorporated into routine Estate Service Co-ordinators' insues raised with Estate Maintenance Team/Housing Repa	
Question	5.14 Are the floor surfaces on the escape route (internal and external) free from trip/slip hazards?	Low Risk
Question	5.15 Are Fire Service facilities and access to the premises suitable and sufficient?	Low Risk
ACTION	Prominently display at/within main entrance area a premises information box (PIB) containing layout drawings with details of high risk areas; location of emergency cut off valves/switches and room usage for fire brigade use in an emergency. Including location details of known vulnerable residents (EAR List).	
Findings (ISSUE)	Premises information box should be provided in accordance with information supplied in the London Fire Brigade's fire safety guidance note GN70.	Action & Completion By 02/12/2021
ACTION	Inspect windows to ensure they can be opened, to vent smoke if need, by the Fire Brigade.	
Findings (ISSUE)	Make necessary alterations to ensure that the openable vents (windows) to staircase and/or lift lobby enclosure can be readily operable by the fire brigade without the use of a key (other than "budget lock" type square key). Whilst it appears the windows may be opened with a budget key, many of the holes for the key have been blocked with debris.	Action & Completion By 02/12/2021
Question	5.16 Are floor level indicators present and legible?	Yes
Question	5.17 Do Fire Services facilities such as dry/wet risers, door entry/lift overrides appear to be free from damage and vandalism?	Yes
Question	5.18 Are Fire Service facilities and controls for the premises subjected to a suitable system of maintenance and/or repair?	Yes
DRM and WRI	M are inspected, maintained and tested in accordance wit	h relevant British

Standard by contractors working on behalf of Housing Property Services. Inspection/testing records are maintained by the Cyclical Testing Team.

Testing of LFB access switches is incorporated into routine Estate Service Co-ordinators' inspections, with any repair issues raised with Estate Maintenance Team/Housing Repairs Service.

The lift overrides are tested on a monthly basis as part of the PPM maintenance visit carried out by the Lift Contractor.

Section	6. Detection and Warning	
Question	6.1 Do the dwellings (from random sample) appear to have suitable hard wired smoke/heat detection installed?	Low Risk
properties as conclusion of the now installed as inspection/testing	moke/heat detection (to LD2 standard) was installed exten part of the Decent Homes programme between 2004 & 20 e Decent Homes programme, mains powered smoke/heat of part of void property process and the cyclical (5 yearly), do g regime where it is not already provided. It is likely the maj not benefit from mains powered detection systems, althoug systems (battery operated) are likely to exist.)10. Since the detection (LD2) is omestic electrical iority of leasehold
Question	6.2 Are methods of detection and warning within the premises considered suitable and sufficient?	Low Risk

Section	7. Emergency Plans	
Question	7.1 Based upon the overall risk of fire, evaluation of fire hazards and means of escape, is the policy of "Stay put, unless affected by smoke or fire" considered adequate for the dwellings within these premises?	Yes
Question	7.2 Based upon the overall risk of fire, evaluation of fire hazards and means of escape, is the policy of "Full Evacuation" considered adequate for the dwellings within these premises?	N/A
Question	7.3 Have emergency plans been communicated to residents and other relevant people	Yes

Fire action notice displayed in entrance lobby to block.

The majority of purpose built blocks of flats operate on the principle that residents should 'stay put, unless directly affected by smoke, heat or fire'. This is communicated to residents through the tenant sign-up pack, regular newsletter articles and the Islington Council website, which also links to the LFB's 'know the plan' website. Caretakers are informed through periodic training.

Section	8. Further Surveys and Investigation	
Question	8.1 Are there any serious or suspected structural deficiencies which could lead to spread of fire beyond the dwelling of origin, warranting further investigation such as a Type 2, 3 or 4 survey?	Νο
Question	8.2 Are there any un-accessed areas or known voids that warrant further investigation to confirm adequate fire safety measures are in place?	Νο
Question	8.3 Are the external escape staircases and gangways for the premises subjected to a suitable system of periodic inspection, maintenance and repair?	N/A

Estate Service Co-ordinators' inspections include all external staircases, gangways and other such areas associated with a particular block. Defects are raised via Estate Maintenance Team/Housing Repairs Service and monitored to completion through the inspection process.

Question	8.4 Are there other types of occupancy forming part of/or within the block (shops, offices, nurseries etc)?	Νο
Question	8.5 Are there any other issues which may have an impact on the fire safety of the premises?	Νο
Question	8.6 Are the external surfaces of the building likely to promote fire spread?	Medium Risk
ACTION	The building exterior consists of infill panels. Consideration should be given to testing the panels to ensure they do not promote the spread of flame across their surface and are suitable for the height of the building.	
Findings (ISSUE)	Infill panels are present under windows at each end of the block.	Action & Completion By 02/12/2021

Section 9. Overall Assessment of Fire Risk	
--	--

Question	9.1 Evaluation of overall fire hazard	Normal
Question	9.2 Evaluation of overall consequences for life safety	Moderate Harm
Question	9.3 Overall evaluation of fire risk	Moderate
Question	9.4 The most appropriate fire strategy for this building is	Stay-put
Stay put unless	s directly affected by fire, heat, smoke or asked to leave b	y the Fire Service.
Question	9.5 Height of Building	N/A
Question	9.6 Next FRA Due	N/A

Audit Details

Section	4. Evaluating the Fire Hazards
Action Ref	0037126
Question	4.2 Does electrical equipment or wiring appear to be free from damage or misuse?
Action Required	Repair operation of defective door release buttons.
Action Notes	{REDACTED}
Due Date	02/12/2021
Responsible	Estate Maintenance Team
Status	COMPLETE
Action Ref	0037127
Question	4.5 Are the common and landlord areas of the premises free from an accumulation of combustible materials, storage and/or waste?
Action Required	Clear waste/storage/combustibles from common/Landlord areas and advise residents of the policy for waste disposal and take enforcement action where appropriate.
Action Notes	{REDACTED}
Due Date	01/06/2021
Responsible	Area Housing Office - Tenancy Management
Status	COMPLETE
Action Ref	0037128
Question	4.5 Are the common and landlord areas of the premises free from an accumulation of combustible materials, storage and/or waste?
Action Required	Clear waste/storage/combustibles from common/Landlord areas and advise residents of the policy for waste disposal and take enforcement action where appropriate.

Action Notes	{REDACTED}
Due Date	01/06/2021
Responsible	Area Housing Office - Estate Services
Status	OPEN
Action Ref	0037129
Question	4.3 Have satisfactory measures been taken to reduce the risk of arson?
Action Required	Secure doors, cupboards, risers etc to prevent unauthorised access.
Action Notes	{REDACTED}
Due Date	02/12/2021
Responsible	Area Housing Office - Estate Services
Status	COMPLETE
Section	5. Means of Escape
Action Ref	0037130
Question	5.15 Are Fire Service facilities and access to the premises suitable and sufficient?
Action Required	Prominently display at/within main entrance area a premises information box (PIB) containing layout drawings with details of high risk areas; location of emergency cut off valves/switches and room usage for fire brigade use in an emergency. Including location details of known vulnerable residents (EAR List).
Action Notes	Premises information box should be provided in accordance with information supplied in the London Fire Brigade's fire safety guidance note GN70.
Due Date	02/12/2021
Responsible	Estate Maintenance Team
Otatura	OPEN
Status	

Action Ref	0037131
Question	5.15 Are Fire Service facilities and access to the premises suitable and sufficient?
Action Required	Inspect windows to ensure they can be opened, to vent smoke if need, by the Fire Brigade.
Action Notes	Make necessary alterations to ensure that the openable vents (windows) to staircase and/or lift lobby enclosure can be readily operable by the fire brigade without the use of a key (other than "budget lock" type square key). Whilst it appears the windows may be opened with a budget key, many of the holes for the key have been blocked with debris.
Due Date	02/12/2021
Responsible	Cyclical Improvement Programme (CIP)
Status	OPEN
Action Ref	0037132
Question	5.7 Are dwelling front entrance doors (from random sample) of a suitably fire resisting construction for the type of property and the location?
Action Required	Inspect front entrance door to ensure it provides 30 minutes' fire resistance.
Action Notes	{REDACTED}
Due Date	01/06/2021
Responsible	Area Housing Office - Tenancy Management
Status	OPEN
Action Ref	0037133
Question	5.7 Are dwelling front entrance doors (from random sample) of a suitably fire resisting construction for the type of property and the location?
Action Required	Replace damaged front entrance door to flat.
Action Notes	{REDACTED}

Due Date	01/06/2021
Responsible	Area Housing Office - Tenancy Management
Status	OPEN
Action Ref	0037134
Question	5.9 Are the fire doors within the common and landlord areas suitable and sufficient, and fitted where necessary, with intumescent strips and smoke seals?
Action Required	Repair/adjust door installation to ensure that the door/s fully self closes into its/their frame/s.
Action Notes	{REDACTED}
Due Date	01/06/2021
Responsible	Estate Maintenance Team
Status	OPEN
Action Ref	0037135
Question	5.9 Are the fire doors within the common and landlord areas suitable and sufficient, and fitted where necessary, with intumescent strips and smoke seals?
Action Required	Remove vents and repair/replace door to provide 30 minutes fire resistance
Action Notes	{REDACTED}
Due Date	02/12/2021
Responsible	Fire Safety Works Team
Status	OPEN
Section	8. Further Surveys and Investigation
Action Ref	0037125

Question	8.6 Are the external surfaces of the building likely to promote fire spread?
Action Required	The building exterior consists of infill panels. Consideration should be given to testing the panels to ensure they do not promote the spread of flame across their surface and are suitable for the height of the building.
Action Notes	Infill panels are present under windows at each end of the block.
Due Date	02/12/2021
Responsible	Fire Safety Works Team
Status	OPEN

Previous O/S Actions (as of report generation date)

None